

Date: Wednesday, 19/03/2008 11:28:59 AM
 User: Linda Lacelle

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.		Drawing Name	: D2656-13		
Job Number	: 38110		Part Number	: D265613		
Estimate Number	: 10804		Drawing Number	: R08-017		
P.O. Number	:		Project Number	:		
This Issue	: 19/03/2008	S.O. No. :	Drawing Revision	:		
Prsht Rev.	: NC		Material	:		
First Issue	: / /	Type : SMALL /MED FAB	Due Date	: 26/03/2008		Qty: 2 Um: Each
Previous Run	: 00015					
Written By	:					
Checked & Approved By	:					
Comment	:					

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	QC5	INSPECT WORK TO CURRENT STEP
<i>Job 03/19 (2)</i>		
2.0	D265613	Wearplate
<i>Comment: INSPECT WORK TO CURRENT STEP</i>		
3.0	PACKAGING 1	PACKAGING RESOURCE #1
<i>Comment: PACKAGING RESOURCE #1</i>		
Re-identify, with a new B#, and return to stock.		
Location: <i>FP 19 AS 08/03/20 (x2)</i>		
4.0	QC21	FINAL INSPECTION/W/O RELEASE
<i>Comment: FINAL INSPECTION/W/O RELEASE</i>		
<i>AS 08/03/20 (x2) 08/03/2015</i>		

Job Completion



U 08.03.28